

# ADA Transition Plan Criteria Analysis

of the  
Town of Arlington, MA

## LEGEND


Analysis Total Score

- 1 - 2
- 3
- 4 - 9

- Ramp (Non-Compliant)
- Sidewalk Condition (Poor)
- Tree Impact (High)
- Tree Impact (Medium)
- Public School
- Highway
- Major Road
- Public / Private Road
- Minuteman Bikeway
- Brook / Stream (surface)
- Brook / Stream (subsurface)
- Water Body
- Town Boundary

# DRAFT

Layer	Buffer (feet)	Value
Active Recreation Facilities	150	1
Central Business Districts	0	1
Churches	150	1
Elderly Facilities	150	1
Environmental Justice Areas	0	1
High Density Residential Properties	150	1
Housing Authority Properties	150	1
MassDOT Top Crash Clusters	0	1
MBTA bus stops	50	1
Minuteman Bikeway public access points	150	1
Post Offices	150	1
Roads - Federal Aid Eligibility	50	1
Schools - Public, Private, Daycare	150	1
Town Buildings for Public Use	150	1
Walk Routes to Schools	50	1



# DRAFT

The information shown on this map is from the Arlington Geographic Information System (GIS) database and is intended for informational purposes only. The Town of Arlington has made reasonable efforts to ensure accuracy of the content, but does not guarantee the accuracy of the information. Users are responsible for determining its suitability for their intended use or purpose.

Map created by the Arlington GIS Office, 6/21/2016.